

CofCF

PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Application of:)	
		:	Examiner: K. Ramsey
HIDEHIKO FUJIMURA, ET AL.)	
		:	Group Art Unit: 2879
Application No.: 09/309,766)	
		:	
Filed: May 11, 1999)	
		:	
For:	METHOD FOR MANUFACTURING)	January 30, 2006
	AIRTIGHT VESSEL AND IMAGE-	:	
	FORMING APPARATUS USING)	
	AIRTIGHT VESSEL	:	
)	Certificate
U.S. Patent No. 6,860,779 B2		:	FEB 0 6 2006
)	
Issued	1: March 1, 2005	: ,	of Correction
			01 00

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

02/01/2006 HALI11

01 FC:1811

00000008 6860779

100.00 BP

REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes and mistakes which are not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction. Any additional fee required by this paper may be charged to Deposit Account No. 06-1205.

Patentees' undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our below-listed address.

Respectfully submitted,

Scott D. Malpede

Attorney for Patentees Registration No. 32,533

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

SDM\mm

DC_MAIN 203793v1

CERTIFICATE OF CORRECTION

PATENT NO.

: 6,860,779 B2

DATED

March 1, 2005

INVENTOR(S) :

HIDEHIKO FUJIMURA, ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

[56] REFERENCES CITED:

FOREIGN PATENT DOCUMENTS, "WO WO 98/264443 6/1998"

should read -- WO WO 98/26443 6/1998--.

OTHER PUBLICATIONS, After "C.A. Spindt, et al.,": "(D cemb r" should read

- --(December--; and after "G. Dittmer,": Discontinous" should read
- --Discontinuous--.

COLUMN 1:

Line 38, "(Elinon" should read --(Elinson--.

COLUMN 9:

Line 20, "degassing" should read --degas--.

COLUMN 15:

Line 34, "raw" should read --row--.

Line 41, "was T4" should read --T4 was--.

COLUMN 17:

Line 9, "degassed" should read --degas--.

MAILING ADDRESS OF SENDER:


FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30)

PATENT NO. 6,860,779 B2

No. of add'l. copies @ 30¢ per page





CERTIFICATE OF CORRECTION

PATENT NO.

6,860,779 B2

DATED

March 1, 2005

INVENTOR(S) :

HIDEHIKO FUJIMURA, ET AL.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 18:

Line 11, "trough" should read --through--.

DC_MAIN 203792v1

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30)

PATENT NO. <u>6,860,779 B2</u>

No. of add'l. copies @ 30¢ per page



CERTIFICATE OF CORRECTION

PATENT NO.

6,860,779 B2

DATED

March 1, 2005

INVENTOR(S) :

HIDEHIKO FUJIMURA, ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

[56] REFERENCES CITED:

FOREIGN PATENT DOCUMENTS, "WO WO 98/264443 6/1998"

should read --WO WO 98/26443 6/1998---.

OTHER PUBLICATIONS, After "C.A. Spindt, et al.,": "(D cemb r" should read

- --(December--; and after "G. Dittmer,": Discontinous" should read
- --Discontinuous--.

COLUMN 1:

Line 38, "(Elinon" should read --(Elinson--.

COLUMN 9:

Line 20, "degassing" should read --degas--.

COLUMN 15:

Line 34, "raw" should read --row--.

Line 41, "was T4" should read --T4 was--.

COLUMN 17:

Line 9, "degassed" should read --degas--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30)

PATENT NO. 6,860,779 B2

No. of add'l. copies @ 30¢ per page



CERTIFICATE OF CORRECTION

PATENT NO.

6,860,779 B2

DATED

March 1, 2005

INVENTOR(S) :

HIDEHIKO FUJIMURA, ET AL.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 18:

Line 11, "trough" should read --through--.

DC_MAIN 203792v1

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30)

FEB 62006



PATENT NO. 6,860,779 B2